

Connector	Goes to Pin
Conn1-1	input +5V
Conn1-2	GND
Conn1-3	ADXL pin 4 (self test)
Conn1-4	ADXL pin 6 (Xout)
Conn1-5	MMA7331L pin 2 (Xout)
Conn1-6	MMA7331L pin 3 (Yout)
Conn1-7	MMA7331L pin 4 (Zout)
Conn1-8	ISZ-650 pin 14 (Z4.5out)
Conn1-9	ISZ-650 pin 20 (Zout)
Conn1-10	input +3.3V
Conn2-1	GND
Conn2-2	IDG-650 pin 23 (Ptats)
Conn2-3	IDG-650 pin 20 (Yout)
Conn2-4	IDG-650 pin 1 (Xout)
Conn2-5	IDG-650 pin 7 (X4.5out)
Conn2-6	IDG-650 pin 14 (Y4.5out)
Conn2-7	ISZ-650 pin 24 (Ptats)
Conn2-8	MMA7331L pin 7 (sleep_bar)
Conn2-9	MMA7331L pin10 (g-sel)
Conn2-10	MMA7331L pin13 (self-test)